INSTALLATION AND ASSEMBLY INSTRUCTIONS XLCS / XLCM / XLCL Series HSS HOUSE SIDE SHIELD



WARNING: Failure to follow instructions could result in damage to product and void warranties!

WARNING: Risk of fire or electrical shock. Disconnect power before installing or servicing.


WARNING: Before proceeding, read all instructions carefully to ensure proper and safe installation.

IMPORTANT: This product must be installed in accordance with the applicable installation code by a person familiar with the construction and operation of the product and the hazards involved.

IMPORTANT: This HSS kit is ONLY for use on LSI Industries models XLCS, XLCM, or XLCL!


Tools required: Size T25 Torx screw driver.

1. With HSS in hand, hold HSS up to luminaire. Locate the side you want to omit light from shining to. Align holes in HSS to holes in luminaire. Using size T25 Torx screw driver, remove ONLY the (4) screws needed to install HSS, as shown below.



CAUTION! Do NOT remove all screws! Optic Unit will become loose and VOID WARRANTY!

2. Place shield on luminaire as shown below. Re-install all (4) screws and tighten evenly to 15 IN-LBS.



NOTE: HSS may be rotated from shown above, depending on model.



Installation Questions?
Call LSI Field Service Department at:
1-800-436-7800 Ext. 3300
Fax: 1-877-861-1368

LSI Industries Inc. 10000 Alliance Road 573982 Rev. 9/15

Cincinnati, Ohio 45242

(513) 793-3200

Fax (513) 793-0147

www.lsi-industries.com
© LSI Industries Inc.

1/1