XLPG LED INSTALLATION AND ASSEMBLY INSTRUCTIONS



SMARTVISION®

CAUTION: Risk of shock. Disconnect power before installing or servicing.

WARNING: Before proceeding, read all instructions carefully to insure proper and safe installation.

WARNING: Risk of electrical shock. High temperatures inside luminaire. Make certain line voltage corresponds with ballast/driver primary voltage (see ballast/driver label).

WARNING: All wiring to be performed per National Electrical Code and local code by a qualified electrician.

IMPORTANT: Not every unit is identical. Placement of proper luminaire is important. Refer to layout drawing to verify location identification, product location, and feed points.

IMPORTANT: Do not electrically connect to live wiring.



Installation Questions?
Call LSI Field Service Department at:
1-800-436-7800 Ext. 3300 Fax 877-861-1368


LSI Industries Inc. ◆ 10000 Alliance Road ◆ Cincinnati, OH 45242 ◆ 513-793-3200 ◆ Fax (513) 793-0147 ◆ www.lsi-industries.com


Page 1 of 2 534357B

XLPG LED INSTALLATION AND ASSEMBLY INSTRUCTIONS


Crossover

SMARTVISION®






* FOR 220/240/480V THE COMMON WIRE IS REPLACED WITH HOT.



- 1.) ATTACH BRACKETS TO BUILDING STRUCTURE (2 PER FIXTURE).
- 2.) THEN LIFT FIXTURE INTO BRACKETS AND SNAP SECURE INTO PLACE ON BOTH ENDS.
- * FIXTURE MAY BE SUPPLIED WITH HEAVY DUTY MOUNTING BRACKETS (HDMB) FACTORY INSTALLED. (PENDANT AND LOCKING NUTS BY OTHERS)
- 3.) MAKE APPROPRIATE WIRE CONNECTIONS. (SEE DIAGRAM)
- 4.) PUSH WIRE NUTS INTO NIPPLE CONNECTION ONE AT TIME AND THEN TIGHTEN CONDUIT FITTING OVER NIPPLE.
- 5.) BATTERY BACK-UP OPTION SEE MANUFACTURERS INSTRUCTIONS PACKED WITH FIXTURE.



- 7.) IF FIXTURE NEEDS TO BE SERVICED OPEN THE LATCHES ON HOUSING TO REMOVE LENS. UNSCREW THE FOUR (4) SCREWS TO REMOVE THE REFLECTOR TRAY FOR ACCESS.
- 8.) REPLACE COMPONENTS AND LOCK LATCHES BACK INTO PLACE WHEN FINISHED SERVICING.



Installation Questions?
Call LSI Field Service Department at:
1-800-436-7800 Ext. 3300 Fax 877-861-1368



LSI Industries Inc . • 10000 Alliance Road • Cincinnati, OH 45242 • 513-793-3200 • Fax (513) 793-0147 • www.lsi-industries.com